Exhibit "A"

IN THE UNITED STATES DISTRICT COURT FOR THE EASTERN DISTRICT OF PENNSYLVANIA

7 TH & ALLEN EQUITIES,	:
Plaintiff,	: : : CIVIL ACTION NO. 5:11-01567-JKG
V.	:
HARTFORD CASUALTY INSURANCE COMPANY,	: : :
Defendant.	:

ORDER

AND NOW, this day of , 2012, upon consideration of Plaintiff's Motion in Limine to Preclude Defendant from Proffering Evidence or Argument at the Trial Hereof Regarding the International Fire Code, the International Building Code, or that Plaintiff Failed to Maintain the Interior Temperature of the Third Floor of the Subject Building Above Forty Degrees Fahrenheit, Defendant Hartford Casualty Insurance Company's Opposition thereto, and the record as a whole, it hereby is **ORDERED and DECREED** that the said motion is **DENIED**.

BY THE COURT:	

IN THE UNITED STATES DISTRICT COURT FOR THE EASTERN DISTRICT OF PENNSYLVANIA

7TH & ALLEN EQUITIES,

Plaintiff,

CIVIL ACTION NO. 5:11-01567-JKG

v.

HARTFORD CASUALTY INSURANCE

COMPANY,

Defendant.

BRIEF OF DEFENDANT HARTFORD CASUALTY INSURANCE COMPANY IN OPPOSITION TO PLAINTIFF'S MOTION IN LIMINE TO PRECLUDE DEFENDANT FROM PROFERRING EVIDENCE OR ARGUMENT AT THE TRIAL HEREOF REGARDING THE INTERNATIONAL FIRE CODE, THE INTERNATIONAL BUILDING CODE, OR THAT PLAINTIFF FAILED TO MAINTAIN THE INTERIOR TEMPERATURE OF THE THIRD FLOOR OF THE SUBJECT BUILDING ABOVE FORTY DEGREES FAHRENHEIT

Defendant Hartford Casualty Insurance Company ("Hartford"), by its undersigned counsel, hereby presents the following Brief in Opposition to Plaintiff's Motion in Limine to Preclude Defendant from Proffering Evidence or Argument at the Trial Hereof Regarding the International Fire Code, the International Building Code, or that Plaintiff Failed to Maintain the Interior Temperature of the Third Floor of the Subject Building Above Forty Degrees Fahrenheit, as follows:

I. FACTS

On November 2, 2012, this Court entered an Order granting in part and denying in part Hartford's motion for summary judgment. (See Docket No. 96). This Court affirmatively found that the Policy's coverage exclusion applies because "the Property was unambiguously vacant as defined by the Policy" and "it is undisputed that the First Loss involved sprinkler leakage." (Id.

at 16). The only issue related to coverage left to be determined at trial is whether an exception to the Policy exclusion applies, *i.e.*, whether Plaintiff protected the system against freezing. (*Id.* at 17).

On November 6, 2012, Plaintiff filed a Motion for Leave to File a Motion in Limine seeking to preclude Defendant from proffering evidence or argument of the International Fire Code or the International Building Code. (See Docket No. 98). Plaintiff also seeks to preclude Defendant from arguing at trial that Plaintiff failed to maintain the temperature of the third floor of the subject building above 40 degrees Fahrenheit. (Id.) In support of its motion in limine, Plaintiff relies upon a portion of this Court's opinion, which states:

[T]he Policy does not refer to the International Fire Code and the International Building Code, which require that the interior of buildings with a wet-sprinkler system be heated to a minimum of 40 degrees Fahrenheit. Furthermore, defendant has not established that the third floor temperature was below 40 degrees at the time of the March 4, 2009 incident.

(Docket No. 96 at 21).

II. LEGAL AUTHORITY

Under the Federal Rules of Evidence 402, evidence is relevant if "it has any tendency to make a fact more or less probable than it would be without the evidence." Fed. R. Evid. 401. All relevant evidence is admissible, unless its "probative value is substantially outweighed by a danger of . . . unfair prejudice, confusing the issues, misleading the jury, undue delay, wasting time, or needlessly presenting cumulative evidence." Fed. R. Evid. 402; 403. However, "there is a strong presumption that relevant evidence should be admitted, and thus for exclusion under Rule 403 to be justified, the probative value of evidence must be substantially outweighed by the problems in admitting it. As a result, evidence that is highly probative is

exceptionally difficult to exclude." Coleman v. Home Depot, Inc., 306 F.3d 1333, 1343-44 (3rd Cir. 2002) (internal citations omitted) (emphasis added).

III. ARGUMENT

The International Fire Code, the International Building Code, and evidence that Plaintiff failed to maintain the third floor of the Building above 40 degrees Fahrenheit are highly relevant and probative of the sole remaining coverage issue in this case: whether the exception to the Policy exclusion applies because Plaintiff protected the sprinkler system against freezing.

At trial, Plaintiff has the burden of proving that the exception to the Policy exclusion applies. 7th & Allen Equities v. Hartford Cas. Ins. Co., C.A. No. 11-01567, slip op. at 21 (E.D. Pa. Nov 2, 2012) (Gardner, J.) (citing Northern Insurance Company of New York v. Aardvark Associates, Inc., 942 F.2d 189, 195 (3d Cir. 1991)). As such, the commentary contained in the Summary Judgment Order that "defendant has not established that the third floor temperature was below 40 degrees at the time of the March 4, 2009 incident" is not determinative of whether the exception applies because this is not Defendant's burden to satisfy.

Additionally, the requirements of the International Fire Code and the International Building Code, including NFPA 25, which have been adopted by the City of Allentown, are highly relevant and probative as to whether Plaintiff protected the sprinkler system against freezing. NFPA 25 tells building owners what they must do to protect wet sprinkler systems from freezing. (HSUF at ¶ 25, Docket No. 38-1). Sprinkler maintenance companies, including Kistler O'Brien whom Plaintiff engaged to maintain the sprinkler system in the Building, follow NFPA 25 when performing inspections of wet sprinkler systems. In fact, an agreement between Plaintiff and Kistler O'Brien, dated October 28, 2004, specifically states that Kistler O'Brien will perform inspections of the Building's sprinkler system pursuant to NFPA 25 and that "N.F.P.A. 25, the standard for the inspection, testing and maintenance of water based fire protection,

specifies that the owner has the responsibility of maintaining the system(s)." See Kistler O'Brien Renewal Agreement dated 10/28/04, attached hereto as Exhibit 1. Kistler O'Brien then inspected the Building's sprinkler system on November 4, 2004 and noted at that time that Plaintiff was not in compliance with NFPA 25 because "[t]he unoccupied parts of the building do not have heat, pipes could freeze and brake [sic]." Kistler O'Brien Sprinkler System Inspection Report, attached hereto as Exhibit 2, at 2. Kistler O'Brien then made recommendations to Plaintiff, based on NFPA 25, that Plaintiff needed to heat the second and third floors of the subject building in order to prevent freezing of the sprinkler system. (HSUF at ¶¶ 28-29, Docket No. 38-1). Plaintiff refused to follow Kistler O'Brien's recommendations and, as a result, Kistler O'Brien notified Plaintiff that it would no longer certify the Building's sprinkler system because the Building was not being properly maintained. (HSUF at ¶ 31, Docket No. 38-1). Instead of correcting the deficiencies raised by Kistler O'Brien, Plaintiff simply chose to stop conducting annual sprinkler inspections. Less than two years after Kistler O'Brien refused to continue inspections unless and until Plaintiff adhered to its recommendations, the sprinkler system suffered the subject freeze event in March 2009.

Therefore, the International Fire Code and the International Building Code, specifically NFPA 25-5.2.5, are highly relevant as to whether Plaintiff met the requirements under the Policy to protect the sprinkler system from freezing. Likewise, evidence that Plaintiff failed to maintain a temperature of greater than 40 degrees, at least, on the third floor of the Building is highly relevant and probative as it supports Hartford's proofs that Plaintiff failed to protect the sprinkler system from freezing. As this evidence is highly relevant and probative, there is a strong presumption that it should be admitted at trial and this evidence "is exceptionally difficult to

exclude." Coleman, 306 F.3d at 1343-44. Accordingly, Plaintiff's motion in limine must be denied.

Respectfully submitted,

ANSA ASSUNCAO LLP

s/Michael J. O'Neill

MICHAEL J. O'NEILL, ESQ. Michael.O'Neill@ansalaw.com Ansa Assuncao LLP 1600 JFK Boulevard, Suite 900 Philadelphia, PA 19103 Telephone: (267) 528-0750

Facsimile: (267) 528-0726

Attorneys for Defendant, Hartford Casualty Insurance

Company

Dated: November 8, 2012

CERTIFICATE OF SERVICE

I, Michael J. O'Neill, hereby certify that, on this 8th day of November, 2012 a true and correct copy of Defendant's Brief in Opposition to Plaintiff's Motion in Limine to Preclude Defendant from Proffering Evidence or Argument at the Trial Hereof Regarding the International Fire Code, the International Building Code, or that Plaintiff Failed to Maintain the Interior Temperature of the Third Floor of the Subject Building Above Forty Degrees Fahrenheit has been served on the following counsel of record via the Court's Electronic filing system:

Mark S. Kancher, Esquire The Kancher Law Firm, LLC Grove Professional Center 100 Grove Street Haddonfield, NJ 08033

Mark S. Haltzman, Esq. Silverang & Donohoe, LLC 595 East Lancaster Avenue, Ste. 203 St. Davids, PA 19087

Attorneys for the Plaintiff

ANSA ASSUNCAO LLP

s/Michael J. O'Neill

MICHAEL J. O'NEILL, ESQ. Michael.O'neill@ansalaw.com Ansa Assuncao LLP 1600 JFK Boulevard, Suite 900 Philadelphia, PA 19103 Telephone: (267) 528-0750

Telephone: (267) 528-0750 Facsimile: (267) 528-0726

Attorneys for Defendant, Hartford Casualty

Insurance Company

Exhibit 1

02:50pm From-Kistler O'brien

+610-266-7110

T-285 P 002/004 F-021

KISTLER O'BRIEN

FIRE PROTECTION

RENEWAL AGREEMENT Water Based Fire Protection Sprinkler - Foam - Fire Pumps Inspection Service Agreement

N.F.P.A. 25, the standard for the inspection, testing and maintenance of water based fire protection, specifies that the owner has the responsibility of maintaining the system(s). By means of periodic inspections, tests, and maintenance, the equipment shall be shown to be in good operating condition, or any defects or impairments shall be revealed. These tasks shall be performed by personnel who have developed competence through training and experience.

CUSTOMER C/N A08951 PROFESSIONAL PROPERTY MGMNT 3000 Atrium Way, Ste 219 Mt. Laurel, NJ 08054

FACILITY LOCATION ECKERD DRUG BLOG 606 N. 7th Street Allentown, Pa. 18102

Customer agrees to purchase and Kistler O'Brien, the contractor, agrees to provide complete inspection services and total emergency service support for your water based fire protection system equipment as shown below. All work will be performed in accordance with applicable

This Service Agreement covers the following protected areas and systems: (1) WATER SPRINKLER SYSTEM (1) ANTI-FREEZE LOOP The amount to be invoiced and paid by Customer upon completion of each inspection ANNUALLY will be \$ 420.00. Repair work and emergency service will be provided on a time and material basis at a discounted rate of 10% off list price. PLUS ST

Special Instructions

INSPECTIONS due OCTOBER 2004

Pricing is based on all work being performed during normal business hours, Monday through Friday (holidays excluded), 7:30 a.m. to 4:00 p.m.

This Agreement shall remain in effect for one year(s) beginning at Date of Execution and shall remain in effect until, and unless, cancelled by either party, in writing, with no less than thirty (30) days notice from date of termination will become effective. This Agreement will automatically renew unless terminated. Renewal agreement will be faxed for your review and CONSIDERATION...

The 2^{ND} page of this document contains important information including a description of functions provided during inspections and a limitation of liability and warranty.

KISTLER O'BRIEN FIRE PROTECTION FED ID# 23-17296 79	7+h + Allen Equities
FIRE PROTECTION FED ID# 23-17296-79 MARLENE M. STERNER	CUSTOMER
By Meden m. Sterm	BY BRIAN HANNAN
Title Service Contract Coordinator	Total Destrict of the second
Date September 28, 2004	TITLE PROPERTY MANAGER
DIRECT # (610) 231-0121	Date_/0/23/04

2210 City Line Road, Belhleheni, PA 18017 610-266-7100 800-322-9060 610-266 7110 Fax

Exhibit

T-285 P 001/004 F-021

KISTLER-O'BRIEN FIRE PROTECTION

2210 City Line Road Bethlehem, Pa. 18017
DIRECT # (610) 231-0121 Fax (610) 266-7110
FAX COVER SHEET
INSPECTION AGREEMENT

TO:

BRIAN HANNAN

DATE: 9/28/04

COMPANY:

PPMI

FAX:

(856) 727-3559

"URGENT"

REQUIRED INSPECTIONS

FROM

MARLENE M. STERNER

Pages (With Cover Letter): 4

Inspections are required per the National Fire Protection Association, the Local Codes and the Insurance Carriers.........

>>>>> We <u>must</u> have written authorization (service agreement)or your Purchase Order <u>before</u> we can schedule any service.

>>>>>Please return the signed Service Agreement and page 2 or your Purchase Order, if PO #'s are a requirement of your company, Via Fax (610) 266-7110 to my attention

Thank you for your time and consideration in this most important matter.....

We look forward to your reply and of being of service to you once again.

KISTLER-O'BRIEN FIRE PROTECTION is a FULL SERVICE COMPANY

Portable Fire Extinguishers are required to be inspected Annually

We can perform the required inspections on your Portable Fire Extinguishers and all your systemsFM 200, Halon, CO2, Inergen, Pre-Action, Fire Alarm, Dry Chem, Sprinkler, Backflow, Fire Pumps, Anti-Freeze, Standpipes, Restaurant systems, Emergency Lighting and more!

We also can provide (3) types of Fire Training for your employees.

Please call me if you have any questions or have any interest in the above at my direct # (610) 231-0121 or the 800# 322-9060, Ext. 121.

T-285 P 003/004 F-021

PAGE 2

WATER BASED FIRE PROTECTION FUNCTIONS PROVIDED DURING EACH INSPECTION - ANNUALLY, QUARTERLY

- Alarm devices operation, functional
- Control valves condition, operation, security
- 3. Gauges condition and operation
- 4. Buildings heating condition, coverage
- 5 Inspect hangers and bracing including seismic bracing
- 6. Pipe and filtings condition visually from external view and only exposed piping
- 7. Sprinklers to be visually inspected for proper temperature, quantity, location/spacing
- 8. Verify spare sprinklers and storage cabinet
- 9. Fire department connections location and operation, also visual
- 10. Main drain condition and operation where permissible.

Inspection Procedures - Various System Types

ANTI-FREEZE SYSTEM:

 Visually inspect installation. Test solution to verify temperature. (This service would be in addition to the regular inspection cost).

DRY SYSTEM

- 1. Perform trip test.
- Verify air compressor operation and oil level.
- Verify operation of low air alarm.
- 4. Perform all other normal procedures (1-10 above) that apply to Wet/Dry systems.

PRE-ACTION & DBLUGE SYSTEM:

All rounal procedures (1-10 above) that apply to Wet/Dry systems, with the addition of venifying detection and
points of activation.

POAM SYSTEM:

- l. Check tank condition.
- Test components of tank and all control valves.
- Take foam sample and verily condition.
- If requested, refract test and viscosity testing. (This service would be in addition to the regular inspection cost).
 Drainage and control to be supplied by others.
- Verify water supply.
- Check checharge devices.
- Test four pump, if applicable.
- 8. Venity condition of any spare foam.
- Testing and maintenance of backflow prevention devices required on foam systems.

Private Fire Service Maintenance, Testing & Inspection

HYDRANTS:

- Flow and flush.
- 2. Operation.
- Visually inspect condition.

FIRE PUMPS - ANNUAL FLOW TEST:

- Operation of pump and controller.
- Full flow test.
- 3. Record and graph results.

LIMITATION OF WARRANTY AND LIABILITY:

CONTRACTOR makes no warranty of any kind, express or implied, except that CONTRACTOR will perform the services required by the Contract in a reasonable man standard under the circumstances, and will certify that at the time of the inspection that the (Equipment or System) is operational or will notify OWNER of defects that are discovered that will prevent proper operation of the Equipment or System. OWNER assumes all risk and hability which may result if the defects which are noted on the inspection report are not to Corrected.

Further, CONTRACTOR does not warrant that the Equipment or System will meet or comply with the requirements of any fire safety code or regulation of any state, numerically or other jurisdiction for the OWNER'S particular location.

This warranty supersedes and is in lete of any and all other expressed or implied warranties, which are hereby disclarmed. No representations of CONTRACTOR has the ability to make any representations or promise except as stated herein, in the event that CONTRACTOR is found liable to OWNER for breach of contract or any other cause of action. OWNER agrees that CONTRACTOR'S total liability will be limited to the amount of the contract, or the amount of all said payments thereunder, whichever is less. In no event will CONTRACTOR be liable to OWNER for any incidental or consequential damages of any kind

T-285 P.004/004 F-021

KISTLER O'BRIEN

FIRE PROTECTION

CORPORATE CAPABILITIES

Kistler O'Brien is a full service company providing consultation, system configuration. installation and service of most fire protection systems for business and industry. Few companies can match the expertise of Kistler O'Brien.

Your single source for fire protection...from portable fire extinguishers...to automatic suppression systems...to alarm and detection systems.

We provide:

Equipment, System Layout and Technical Services:

Inergen Suppression Systems FM-200 Suppression Systems Halon 1301 Suppression Systems Low & High Pressure CO₂ Suppression Systems Voice Evacuation Systems

Preaction System Controls Dry Chemical Suppression Systems Kitchen Suppression Systems Fire Alarm & Detection Systems

Sales, Service and Maintenance:

Portable Fire Extinguishers:

- Required Annual Inspection
- . 6 Year Maintenance
- . Fire Safety Training Classes

Pre-Engineered Kitchen Suppression Systems: Required semi-annual inspection

Off-Road Vehicle Systems Spray Booth Protection Room Integrity Testing

Fire Alarm, Inergen, FM-200, CO2, Halon, Dry Chem & Fire Alarm:

- . Semi-annual or annual inspection
- Sprinkler Systems:
- . Monthly, quarterly, semi-annual or annual inspection

Fire Pump Testing Foam Systems

Hose Testing & Inspection **Emergency Lighting & Exit Signs**

Installation Services

By Kistler O'Brien factory-trained personnel By other contractors with Kistler O'Brien assistance and checkout

. Other .

24-Hour Central Station Monitoring 24-Hour Emergency Call Out Service 50 Fully Stocked Service Vehicles U.L. Approved Halon Filling Station U.L. Approved Hydrostatic Testing Facility Factory-Trained, Uniformed Personnel

Kistler O'Brien represents the best names in the business: Siemens Building Technologies, Inc., Fenwal Protection Systems, Kidde Fire Systems, Fire Control Instruments, Ansul Fire Protection, Amerex Fire Extinguishers.

> Rev 09/03 Sup 07/01

2210 City Line Road, Bethlehem, PA 18017 610-266-7100 800 322-9060 610-266-7110 Fax

Exhibit 2

2210 CITY NE ROAD

SPRINKLER SYSTEM INSPECTION REPORT

Page 1 of 2

KISTLER O'BRIEN

BETHLEH , PA 18017

PHONE (610) 266-7100 OR (800) 322-9060

FAX (610) 266-7110

FAX (010) 200 7 1.10	
MPANY NAME & NOT	BUILDING OF LOCATION
DRESS -	Can high Alpha Mil
Will Mill Company	INSPECTOR(S)
TITLE	PHONE / DATE
STOMER CONTACT TITLE	11/04//
GENERAL a. Is the building occupied?	LA MARK RULY
a. Is the building occupied? b. Is occupancy same as previous inspection?	
b. Is occupancy same as previous inspection? Are all systems in service?	
c. Are all systems in service? d. Are all fire protection systems same as last inspection?	7 344
d. Are all fire protection systems same as last inspection? e. Is hazard completely sprinklered?	
e. Is hazard completely sprinklered? f. Are all new additions and building changes properly protected? Are all new additions and building changes properly protected?	
f. Are all new additions and building changes properly protected g. Is all stock or storage properly below sprinkler piping?	in Page 2)
including blind attics, perimeter areas and are all exterior openings	
cold air?	
CONTROL VALVES (See Section 16) a. Are all sprinkler system main control valves open?	
a. Are all sprinkler system main control valves open?	
a. Are all sprinkler system main control valves open? b. Are all other valves in proper position? c. Are all control valves in good condition and sealed or supervised?	
c. Are all control valves in good condition and sealed of super-	
a. Was a water flow test made and results satisfactory?	
a. Was a water flow test made and results stricted by 4. TANKS, PUMPS, FIRE DEPT. CONNECTIONS 4. TANKS, PUMPS, FIRE DEPT. CONNECTIONS	
 TANKS, PUMPS, FIRE DEPT. CONNECTIONS a. Are fire pumps, gravity tanks, reservoirs and pressure tanks in go 	ood condition and properly
a. Are tire pumps, gravity tallid, reserved	
in entiefactory conditions, couplings in	e, caps in place and cneck
b. Are fire dept. connections in satisfactory conditions, valves tight?	
5. WET SYSTEMS (See Section 13)	- 100 mg
5. WET SYSTEMS (See Section 13) a. Have anti-freeze systems been tested and left in satisfactory con	ontrod °F
a. Have anti-freeze systems been tested and left in satisfactory control. Temp of Solution te	v condition?
water flow indicators and relates in satisfactors	7 (5 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
d. Internal inspection of alarm valve Last date performed	
6. DRY SYSTEMS (See Section 14)	
DRY SYSTEMS (See Section 14) a. Is dry valve in service and in good condition?	
and priming water level normal :	
C. Is air compressor in your conditions.	T-chihit
Devised in COMICO	
the shocked for cropping willing past to route.	
h. Have dry valves been trip tested satisfactority as required: i. Are dry valves adequately protected from freezing?	
7. SPECIAL SYSTEMS, DELUGE, PRE-ACTION (See Section	18)
7. SPECIAL SYSTEMS, DELUGE, PRE-ACTION (See Section a. Were valves trip tested? ☐ Partial ☐ Full	Sec.
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
	A
d. Verification of detection. Type of detection e. Verification of low air/supervisory functions	$\Delta \pi \text{ EXHIBIT}$
e. Verification of low air/supervisory functions	Deponent Lry
- 666 - 2011 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
and gong test satisfactory?	Date Rptr. A Date Date Date Date Date Date Date Date
a. Water motor and going test datasets b. Electric alarm test satisfactory?	WWWDEPOBOOLEGOM
b. Electric alarm test satisfactory? c. Supervisory alarm service test satisfactory?	- D 0 Line 18

*Explain "NO" answers on Page 2, Line 18

Page 2 of 2

2 DALL	BUILDING OR LOCATION COATION	$\frac{T}{T}$
ISTOMER NAME PHO.	THE STANCE	
SPRINKLERS - PIPING		25:274085
	, not obstructed, and free of corrosion or loading?	
t the managing of the overlight	10.7	
not to the modern wolves	chack valves nanners, diessure dauges, opon opinimiers,	
e. Are all sprinklers of proper tempera	ature rating?	
f. Are portable fire extinguishers in go	ood condition?	7
	satisfactory?	
Date Dry System Piping last checked f	for proper pitch Partial Full	7***
Date Dry System Piping last checked I	or proper pitch ☐ Pull ☐ Pull ☐ Full ☐	
Date Dry Pipe Valve last trip tested	Make and Model? UIK'1	
3. Wet Systems.	Make and Model?	
4. Dry Systems: Number	Type	
5. Special Systems: Number	Condition?	
Make and Model?	Open Secured Closed Signs	
TO VALVEO	Number 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	III.
6. CONTROL VALVES		Selection of the Selection
City Connection Control Valve		September 1988
Tank Control Valves		
Pump Control Valves Sectional Control Valves		
System Control Valves		
The Garage Control of the Control of	WATER FLOW TEST	.4.
7. Water Pressure?	CITY PSI TANK PSI FIRE PUMP	PSI
Water Pressure? 1711-1711-17	(if none performed, why?)	
Water Flow Test?	Size Pressure Flow	Pressure
Size Pressu	ire Flow Pressure Technique Legated Test Pine Before Pressure	After
Test Pipe Located Test Pipe Before	6 1100000	
MAN DOWN I	_ b' - 'S	
<u> Paragana da Jawa da J</u>	Prior to gase Alam panel had 2 troubles contelat classicion to present parts of the building closed have heat for	٠.
19 Evolunation of any "No" answers:	Trior To Gust Allam DANY MAN & 10000145 CONTEST STORY	AV!
Trubles One Place	The undicated parts of the build of the will have her for	~ /
TOWNER UNITED	(50) Autifrage love is in poor condition (wife) 2000. 18:	2[-]
Could break con Brance	al do I couch to parce 19A) Sa. Al hours in VACA-1 ST	-4 419
Tarpas Et Hem Duille	1 here De pure Silves old Good should be Usle I	3 8 Par .
PS ETEL (76 MOS MELS) 1.	me tal ace toward beauty and have started	Ireking
150 Boil - Univer	on the a wille on a comme	<u> </u>
(尼)		
	and as fire protection equipment they store and of a challent ale	<u> </u>
19. Recent changes in building occupar	ucy or me thorecant ediabate.	
to chede spoully siften		
20. Adjustments or corrections made: _		
		i ·
21. Recommended Improvements:	KISTLER 0034	
21. Recommended improvements	KID122	
	4	
(1)1 ()	*Explain "NO" answers on Page 2, Line 18	1/
	I I LAND IN THE WAY OF THE PARTY OF THE PART	Alle
and WAT I	1104/04 May 11- Junt h 1	77/OT
Technician's Signatu	Customer's Signature/Date	r. i T.
years (REV 12/01)	FILE TO SEE THE SECOND	•

KOB 6650 (REV. 12/01)

Exhibit "B"

02:59pm From-Kfistfer O'brien

+610-266-7118

T-285 P 002/004 F-021

KISTLER O'BRIEN

FIRE PROTECTION

RENEWAL AGREEMENT Water Based Fire Protection Sprinkler - Foam - Fire Pumps Inspection Service Agreement

N.F.P.A. 25, the standard for the inspection, testing and maintenance of water based fire protection, specifies that the owner has the responsibility of maintaining the system(s). By means of periodic inspections, tests, and maintenance, the equipment shall be shown to be in good operating condition, or any defects or impairments shall be revealed. These tasks shall be performed by personnel who have developed competence through training and experience.

CUSTOMER C/N A08951 PROFESSIONAL PROPERTY MGMNT 3000 Atrium Way, Ste 219 Mt. Laurel, NJ 08054

FACILITY LOCATION ECKERD DRUG BLOG 606 N. 7th Street Allentown, Pa. 18102

Customer agrees to purchase and Kistler O'Brien, the contractor, agrees to provide complete inspection services and total emergency service support for your water based fire protection system equipment as shown below. All work will be performed in accordance with applicable

This Service Agreement covers the following protected areas and systems: (1) WATER SPRINKLER SYSTEM (1) ANTI-FREEZE LOOP

The amount to be invoiced and paid by Customer upon completion of each inspection ANNUALLY will be \$ 420.00. Repair work and emergency service will be provided on a time and material basis at a discounted rate of 10% off list price. PLUS ST

Special Instructions

INSPECTIONS due OCTOBER 2004

Pricing is based on all work being performed during normal business hours, Monday through Friday (holidays excluded), 7:30 a.m. to 4:00 p.m.

This Agreement shall remain in effect for one year(s) beginning at Date of Execution and shall remain in effect until, and unless, cancelled by either party, in writing, with no less than thirty (30) days notice from date of termination will become effective. This Agreement will automatically renew unless terminated. RENEWAL AGREEMENT WILL BE FAXED FOR YOUR REVIEW AND CONSIDERATION....

The 2^{ND} page of this document contains important information including a description of functions provided during inspections and a limitation of liability and warranty.

KISTLER O'BRIEN FIRE PROTECTION FED ID# 23-17296-79	7+h + Allen Equities
MARLENE M. STERNER By MARLENE M. STERNER	CUSTOMER
Title Service Contract Coordinator	BY BRIAN HANNAN TICE PROPERTY MAJAGER
Date <u>September 28, 2004</u> DIRECT # (510) 231-0121	Date 10/23/04

2210 City Line Road, Bethlehens, PA 18017 610-266-7100 800-322-9060 610-266 7110 Fax

Exhibit

1271

Sep-28-04 02:59pm From-Kistler O'brien

+610-266-7110

T-285 P 001/004 F-021

KISTLER-O'BRIEN FIRE PROTECTION

2210 City Line Road Bethlehem, Pa. 18017
DIRECT # (610) 231-0121 Fax (610) 266-7110
FAX COVER SHEET
INSPECTION AGREEMENT

TO:

BRIAN HANNAN

DATE: 9/28/04

COMPANY: PPMI

FAX:

(856) 727-3559

"URGENT"

REQUIRED INSPECTIONS

FROM

MARLENE M. STERNER

Pages (With Cover Letter): 4

Inspections are required per the National Fire Protection Association, the Local Codes and the Insurance Carriers.........

>>>>> We <u>must</u> have written authorization (service agreement)or your Purchase Order <u>before</u> we can schedule any service.

>>>>> Please return the <u>signed Service Agreement</u> and page 2 or your <u>Purchase Order</u>, if PO #'s are a requirement of your company, Via Fax (610) 266-7110 to my attention

Thank you for your time and consideration in this most important matter.....

We look forward to your reply and of being of service to you once again.

KISTLER-O'BRIEN FIRE PROTECTION is a FULL SERVICE COMPANY

Portable Fire Extinguishers are required to be inspected Annually
We can perform the required inspections on your Portable Fire Extinguishers and all your
systemsFM 200, Halon, CO2, Inergen, Pre-Action, Fire Alarm, Dry Chem, Sprinkler,
Backflow, Fire Pumps, Anti-Freeze, Standpipes, Restaurant systems, Emergency Lighting
and more!

We also can provide (3) types of Fire Training for your employees.

Please call me if you have any questions or have any interest in the above at my direct # (610) 231-0121 or the 800# 322-9060, Ext. 121.

T-285 P 003/004 F-021

PAGE 2

WATER BASED FIRE PROTECTION FUNCTIONS PROVIDED DURING EACH INSPECTION - ANNUALLY, QUARTERLY

- Alarm devices operation, functional
- Control valves condition, operation, security
- Gauges condition and operation
- Buildings heating condition, coverage
- Inspect hangers and bracing including sciencic bracing
- Pipe and fittings condition visually from external view and only exposed piping
- Sprinklers to be visually inspected for proper temperature, quantity, location/spacing
- Verify space sprinklers and storage cabinet
- Fire department connections location and operation, also visual
- 10. Main drain condition and operation where permissible.

· Inspection Procedures - Various System Types

ANTI-FREEZE SYSTEM:

Visually inspect installation. Test solution to verify temperature. (This service would be in addition to the regular

DRY SYSTEM

- 1. Perform trip test.
- Verify air compressor operation and oil level.
- Verify operation of low air alarm.
- Perform all other normal procedures (1-10 above) that apply to Wet/Dry systems.

PRE-ACTION & DBLUGE SYSTEM:

All normal procedures (1-10 above) that apply to Wet/Dry systems, with the addition of verifying detection and points of activation.

FOAM 5YSTEM:

- 1. Check tank condition.
- Test components of tank and all control valves.
- Take foam sample and verify condition.

 If requested, refract test and viscosity testing. (This service would be in addition to the regular inspection cost). Dramage and control to be supplied by others.
- Verify water supply.
- Check discharge devices.
- Test foam pump, if applicable.
- Venity condition of any spare form.
- Testing and maintenance of backflow prevention devices required on foam systems.

Private Fire Service Maintenance, Testing & Inspection .

HYDRANTS:

- Flow and flush
- Operation.
- Visually inspect condition.

FIRE PUMPS - ANNUAL FLOW TEST:

- Operation of pump and controller.
- Full flow test.
- Record and graph results.

LIMITATION OF WARRANTY AND LIABILITY:

CONTRACTOR makes no warranty of any kind, express or implied, except that CONTRACTOR will perform the services required by the Contract in a reasonable man standard under the circumstances, and will certify that at the time of the inspection that the (Equipment or System) is operational or will notify OWNER of defects that are discovered that will prevent proper operation of the Equipment or System. OWNER assumes all risk and liability which may result of the defects which are noted on the inspection report are not corrected.

Further, CONTRACTOR does not warrant that the Equipment or System will meet or comply with the requirements of any fire safety code or regulation of any state, naunicipality or other jurisdiction for the OWNER'S particular location. This warranty supersedes and is in lieu of any and all other expressed or implied warranties, which are hereby disclaimed. No representative of CONTRACTOR has the ability to make any representations or promise except as stated herein, in the event that CONTRACTOR is found liable to OWNER for breach of contract or any other cause of action. OWNER agrees that CONTRACTOR'S total liability will be limited to the amount of the contract, or the amount of all said pagments thereunder, whichever is less. In no event will CONTRACTOR be liable to OWNER for any incidental or consequential damages of any kind

T-285 P.004/004 F-021

KISTLER O'BRIEN

FIRE PROTECTION

CORPORATE CAPABILITIES

Kistler O'Brien is a full service company providing consultation, system configuration, installation and service of most fire protection systems for business and industry. Few companies can match the expertise of Kistler O'Brien.

Your single source for fire protection...from portable fire extinguishers...to automatic suppression systems...to alarm and detection systems.

We provide:

Equipment, System Layout and Technical Services:

Inergen Suppression Systems
FM-200 Suppression Systems
Halon 1301 Suppression Systems
Low & High Pressure CO₂ Suppression Systems
Voice Evacuation Systems

Preaction System Controls
Dry Chemical Suppression Systems
Kitchen Suppression Systems
Fire Alarm & Detection Systems

Sales, Service and Maintenance:

Portable Fire Extinguishers:

- . Required Annual Inspection
- 6 Year Maintenance
- . Fire Safety Training Classes

Pre-Engineered Kitchen Suppression Systems: Required semi-annual inspection Off-Road Vehicle Systems

Off-Road Vehicle Systems Spray Booth Protection Room Integrity Testing Fire Alarm, Inergen, FM-200, CO₂, Halon, Dry Chem & Fire Alarm:

. Semi-annual or annual inspection

Sprinkler Systems:

. Monthly, quarterly, semi-annual or annual inspection

Fire Pump Testing Foam Systems

Hose Testing & Inspection Emergency Lighting & Exit Signs

Installation Services

By Kistler O'Brien factory-trained personnel
By other contractors with Kistler O'Brien assistance and checkout

Other .

24-Hour Central Station Monitoring
24-Hour Emergency Call Out Service
50 Fully Stocked Service Vehicles
U.L. Approved Halon Filling Station
U.L. Approved Hydrostatic Testing Facility
Factory-Trained, Uniformed Personnel

Kistler O'Brien represents the best names in the business: Siemens Building Technologies, Inc., Fenwal Protection Systems, Kidde Fire Systems, Fire Control Instruments, Ansul Fire Protection, Amerex Fire Extinguishers.

Rev 09/03 Sup 07/01

2210 City Line Road, Bethlehem, PA 18017 610-266-7100 800 322-9060 610-266-7110 Fax

Exhibit "C"

2210 CITY NE ROAD

SPRINKLER SYSTEM INSPECTION REPORT

Page 1 of 2

							-	 IOI		
	- 1	_	-	n	\mathbf{r}	\sim	15.7	 17 11	VI.	
- 1	-	11.7		ν	K.	t .) 1	L P. L	 11.21	N	
			_	•				 		
-			,		•					

KISTLER O'BRIEN BETHLEH , PA 18017
PHONE (610) 266-7100 OR (800) 322-9060 FAX (610) 266-7110

PARTICIPATION AND THE	ING OR LOCATION
1707059 351117055 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	20 MAR & CHARLEN NA
DORESS TOOL Hitchen City Som Dit INSPE	COORS)
ITY/STATE/ZIP	DATE
CUSTOMER CONTACT TITLE PHON	1/04/04
	SE MOST NATIONAL DE LA COMPANIA DEL COMPANIA DE LA COMPANIA DEL COMPANIA DE LA CO
1. GENERAL a, Is the building occupied?	ANT RULY
b. Is occupancy same as previous inspection? c. Are all systems in service?	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
f. Are all new additions and building changes properly protected. g. Is all stock or storage properly below sprinkler piping? h. Was properly free of fires since last inspection? (Explain any fire on Page 2)	
h. Was property free of fires since last inspection? (Explain any life of the second in a reas protected by wet system, does the building appear to be properly.)	neated in all areas,
 In areas protected by wet system, does the building apposition including blind attics, perimeter areas and are all exterior openings protected 	ed against entrance of
cold air?	
2. CONTROL VALVES (See Section 16)	
	A STANCE
a. Are all sprinkler system main control valves open? b. Are all other valves in proper position? c. Are all control valves in good condition and sealed or supervised?	
c. Are all control valves in good condition and sealed or supervised?	
WATER SUPPLIES (See Section 17) a. Was a water flow test made and results satisfactory? The Dept CONNECTIONS	
a. Was a water flow test made and results satisfactory:	
4. TANKS, PUMPS, FIRE DEPT. CONNECTIONS a. Are fire pumps, gravity tanks, reservoirs and pressure tanks in good condi	tion and properly
Are fire dept, connections in satisfactory conditions, couplings free, caps in	n place and check
valves tight?	
a. Have anti-freeze systems been tested and left in satisfactory condition? b. Type of Anti-Freeze Temp of Solution tested	
c. Are alarm valves, water flow indicators and retains in satisfactory of the following control of alarm valve. Last date performed	Condition
a. Is dry valve in service and in good condition?	
by legair pressure and priming water level normal?	
c. Is air compressor in good condition?	
d. Were low points drained during fall and winter inspections? e. Are Quick Opening Devices in service?	Exhibit
been shocked for stopping within hast 10 veats?	505
The piping been checked for proper pitch within past 5 years:	
h. Have dry valves been the tested satisfactory to a compare the first tested satisfactory to a compare the compare the compare the compare the compare th	
Value house and heater condition satisfactory?	
7. SPECIAL SYSTEMS, DELUGE, PRE-ACTION (See Section 18) a. Were valves trip tested? Partial Full	
a. Were valves trip tested? Deartial Deutiment	
- throad rejectated upon completion?	
d. Verification of detection. Type of detection	$\Delta \pi$ EXHIBIT
d. Verification of detection. Type of detection e. Verification of low air/supervisory functions	Deponent Fry
O ALARMS	don't de
Water motor and gong test satisfactory?	Date Rptr. Www.pterobook.com
b. Electric alarm test satisfactory? c. Supervisory alarm service test satisfactory? *Explain "NO" answers on Pa	ge 2. Line 18

Case 5:11-cv-01567-JKG Document 9951-HPNed-\$1/08/12/1-Page 24-of 2

STOMER NAME PPAG.	Section 1	BUILDING	OR LOCATION CA	red form
				ES ENOTE MAC
SPRINKLERS - PIPING a. Are all sprinklers in good condition, n	not obstructed, and free of co	orrosion or loading?		
	?		HARTE STATE OF THE	
 d. Is condition of piping, drain valves, ch 	heck valves, nangers, pressu	ite gauges, open opn		
and the second s				
In hand bose on sprinkler systems Si	atistactory?			
Date Dry System Piping last checked for	r stoppage	3		/**
Date Dry System Piping last checked for Date Dry System Piping last checked for	proper pron		_ Dertial Defull	
Date Dry Pipe Valve last trip tested	Make and Model?	11Kin		
Wel Systems.	Make and Model?			
Dry Systems: Number Special Systems: Number	Type			
Make and Model?		Conditio		
Make and Moder.	expenses report the ROSE SECTION	Open Secured	Jes No Yes No	Condition 44
CONTROL VALVES	SUBMINE STREET	CS NO YOS INC		
City Connection Control Valve				er-eta perenta de la companya de la Na la companya de la
Tank Control Valves			110	
Pump Control Valves				
Sectional Control Valves	054/	171 171	7 / /	2K
System Control Valves	WATER F	LOW TEST		
an t			PSI FIRE F	PUMP PSI
Water Pressure?	0	- :		
Water Flow Test?	(if none performed, why	(r)	O: Dracours	Flow Pressure
Size Pressure	e Flow Pressure	- District	Size Pressure Test Pipe Before	Pressure After
est Pipe Located Test Pipe Before	Pressure After	Test Pipe Located	lest i pe Bolore	
Main Drain 2 75				
(1)30 (2) (3) (2)	· · · · · · · · · · · · · · · · · · ·			101
8. Explanation of any "No" answers:	into Exp Mar	DANY hal	2 troubles Clay	Clar Clerk
8. Explanation of any "No" answers:	Le Derocopiel DAN	Rot He buile	1 a do wel have	hast pipis
rubles ungettach to the	FOR A FRANCE DE	A TELLY DON'T CAN	Sition Coulded	(150.18bc)
ould been con Brake	5p / Hote grove low	1/10/1	Sound heads is	When I grid are
TADES ET Stew 34 174 0	Midal report to	panel 14	11 621 11 11 11 1	West Took
as to 19W most heals in	Aray Ages The	Our 30 450	Tal wood Shover 1)	clast lastin
Col ton Bula Walnes	in Macin WAlve	are Convetted	Berry BOLA DO	A STATION ILENIE
(To				
V.			<u></u>	ê .
		M. Oct	at admirthal	Int GLERSS
19. Recent changes in building occupanc	y or fire protection equipmen	nt: ///////////	F-101 VY 3 11-11	
Fichelle Double sile				
1000000				· ·
			· · · · · · · · · · · · · · · · · · ·	
20. Adjustments or corrections made:				
				1
			- 1	0024
				TR 0034
21. Recommended Improvements:			KISTI	ER 0034
21. Recommended Improvements:			KISTI	ER 0034
21. Recommended Improvements:	44.0	owers on Page 2 Vine		ER 0034
21. Recommended Improvements:	*Explain "NO" an	swers on Page 2, Line		ER 0034
21. Recommended Improvements:	*Explain "NO" an	swers on Page 2, Line	and M. Smit	L 1/4/03
21. Recommended Improvements:	104/04	swers on Page 2, Line		L 1/4/03